






# 1" IMPACT WRENCH

# Model 6910 (MJ)




### WIRING DIAGRAM





**SERVICE CHANGES**

**1. Change on Anvil.**



Item No.	Description	Type 1	Type 2
4	Ring Spring 22	-----	231921-7 (Added)
5	Anvil	325414-5 (No Longer Available)	325587-4
60	Pin	325365-2 (No Longer Available)	(Discontinued)
61	Spring	231213-4 (No Longer Available)	(Discontinued)
62	Slotting Pin	256710-9 (No Longer Available)	(Discontinued)

Above parts are completely interchangeable as a set.

When replacing Type 1 Anvil, replace it with complete set of Type 2 parts.